



3725 Nicholson Rd.
Franksville, WI 53126
unicous.com

**Important Notice Regarding Unico 3100 Series DCR SCR Drives
Important Notice Regarding Unico Drive Pak IIA Inverters
For Immediate Release (December 2023)**

After a long in-service run, various components on the 3100 and Drive Pak Series are no longer available. Unico can no longer assure consistent and reliable support in terms of parts and service these inverters.

Based on component availability, on a case-by-case basis, Unico will attempt to provide replacement parts and service for these products.

In order to preserve the value of your production equipment with minimal investment, Unico recommends replacing the 3100 Series and Drive Pak inverters with Unico's 2400 E-27 Series inverters.

Nearly all applications written for the 3100 and Drive Pak Series have been ported to the E27 product family providing the ability to maintain your production processes with minimal downtime.

Be advised PLC modifications to accommodate changes in communication protocols, Modbus mapping, and other interfaces are required. Installation is typically performed by our Field Service Department.

For further details or to discuss the upgrade path that is best for your plant, please contact your regional Unico office or send an email to unicous@unicous.com

Sincerely,

Mike Lasch
Aftermarket Director (Canada & USA)

Unico, LLC
3725 Nicholson Road
Franksville, WI 53126-0505
Office: 262.594.7435
Mobile: 262.488.1839
mike.lasch@unicous.com
www.unicous.com